

From: KarenD Johnson/R3/USEPA/US
Sent: 2/3/2012 10:15:43 AM

To: Terry Simpson/ESC/R3/USEPA/US@EPA

CC:

Subject: Re: Fw: Cabot QA/QC

Thanks Terry- but I think Rich Rupert is going to be the one who needs this most, I'm going to forward your previous info to him for use with the data spread sheet they are populating including data quality. Thanks for all your work on this!!!
Karen D. Johnson, Chief
Ground Water & Enforcement Branch

From: Terry Simpson/ESC/R3/USEPA/US
To: KarenD Johnson/R3/USEPA/US@EPA
Cc: Cynthia Metzger/ESC/R3/USEPA/US@EPA, Fred Foreman/ESC/R3/USEPA/US@EPA, Cynthia Caporale/ESC/R3/USEPA/US@EPA
Date: 02/03/2012 08:58 AM
Subject: Fw: Cabot QA/QC

Hi, Karen --

I should have been clearer about this in my message. This is not our final analysis. I am still populating the limitations table, but I just wanted to check in as to whether this is what you are looking for.

Terry

Terry Simpson, Regional QA Manager
US EPA Region 3
Environmental Science Center
701 Mapes Road
Ft. Meade, MD 20755-5350

Voice: 410.305.2739
Fax: 410.305.3095
email: simpson.terry@epa.gov

Region 3 QA Website:

<http://www.epa.gov/region03/esc/qa/index.htm>

Only four types of organizations need to worry about data quality:

*Those that care about their customers,
Those that care about profit and loss,
Those that care about their employees, and
Those that care about their futures.*

– Thomas C. Redman (2006)

----- Forwarded by Terry Simpson/ESC/R3/USEPA/US on 02/03/2012 08:55 AM -----

From: Terry Simpson/ESC/R3/USEPA/US
To: KarenD Johnson/R3/USEPA/US@EPA
Cc: Cynthia Metzger/ESC/R3/USEPA/US@EPA, Fred Foreman/ESC/R3/USEPA/US@EPA
Date: 02/02/2012 06:16 PM

Subject: Cabot QA/QC

Hi, Karen --

Just wanted to update you on Ft. Meade's QA/QC review of the existing data from Cabot's initial 104e response. I'm attaching a table and two checklists. We are using the checklists to inventory the amount of QC in each data file. This will serve two purposes: 1) to make a determination whether there is enough QC present to validate the data; and 2) to document exactly which QC information is missing and/or needed, should we want to specifically request it from Cabot and their labs. The table documents each file by report title, date, and analyses. It also provides a recommendation on the limited use of the data and cross-references the affected samples.

[attachment "QA_QC Review of Cabot provided data 03Feb2012.docx" deleted by Terry Simpson/ESC/R3/USEPA/US]
[attachment "Inorganic_Inventory of QC Measures.docx" deleted by Terry Simpson/ESC/R3/USEPA/US] [attachment
"Organic_Inventory of QC Measures.docx" deleted by Terry Simpson/ESC/R3/USEPA/US]

Please take a look at these and let me know your thoughts. Is there anything that you were expecting to see that isn't in here? Thanks!

Terry

Terry Simpson, Regional QA Manager
US EPA Region 3
Environmental Science Center
701 Mapes Road
Ft. Meade, MD 20755-5350

Voice: 410.305.2739
Fax: 410.305.3095
email: simpson.terry@epa.gov

Region 3 QA Website:

<http://www.epa.gov/region03/esc/qa/index.htm>

Only four types of organizations need to worry about data quality:

*Those that care about their customers,
Those that care about profit and loss,
Those that care about their employees, and
Those that care about their futures.*

– Thomas C. Redman (2006)